

Stern, Jeff

From: Tiffany, Bruce
Sent: Thursday, June 15, 2006 9:12 AM
To: Renaud, Rick; Salazar, Raleigh; Stern, Jeff
Subject: FW: Pics
Attachments: Site 1541 060806 pics_0012.JPG; Site 1541 060806 pics_0002.JPG; Site 1541 060806 pics_0003.JPG; Site 1541 060806 pics_0004.JPG; Site 1541 060806 pics_0006.JPG; Site 1541 060806 pics_0008.JPG; Site 1541 060806 pics_0009.JPG; Site 1541 060806 pics_0010.JPG; Site 1541 060806 pics_0011.JPG; Site 1541 060806 pics_0001.JPG; Site 1541 060806pics_0013.JPG; KCIADrains.pdf

Rick, Raleigh, and Jeff;

Here are some photos from the sampling at Vault 1541 (see attached figure for location). As you can see from the photos, there appear to be inputs that are not typical stormwater runoff. It may be difficult to observe from the photos, but there are bubbles on the surface of the floating layer, indicating that there may be an anaerobic process occurring.

Although we do not have analytical results back yet, we have sufficient information to know that further investigation is needed regarding the sources that are tributary to this vault.

Thanks,

Bruce

From: Heinz, Dana
Sent: Wednesday, June 14, 2006 4:11 PM
To: Himes, Tammy; Tiffany, Bruce
Subject: Pics

Bruce and Tammy -

Here are the pictures taken 6/8/06 at site 1541.

Pics. 0011, 0012, 0013 are of a storm drain in the center of the parking lot - we think is draining into the sample site?

Pic. 0013 is of the storm drain in reference to site 1541.

Thanks,

Dana

5/20/2008

KCSlip4 53612

SEA419985